U.S. Patent Application No. 10/716,599

Attorney Docket No.: 57983.000119 Client Reference No.: 15725ROUS02U

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:

Herman KWONG et al.

Appln. No.: 10/716,599

Filed: November 20, 2003

For: TECHNIQUE FOR ACCOMMODATING

ELECTRONIC COMPONENTS ON A

MULTILAYER SIGNAL ROUTING

DEVICE

Group Art Unit: 2827

Examiner: Yuriy Semenenko

Confirmation No.: 7194

Customer No.: 21967

U.S. Patent No.: 7,107,673 B2

Issued: September 19, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Attn: Certificate of Corrections Branch

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT UNDER 37 CFR 1.322(a)

Sir:

is respectfully requested that a Certificate Ιt Correction be issued in the above-identified patent.

Attached two properly completed Certificate are Correction Forms (PTO-1050). It is requested that these forms be certified by the Commissioner, with one form being returned to the undersigned attorney. The undersigned attorney is the attorney of record for the assignee as evidenced by the Assignment recorded at Reel 014728, Frame 0803, and the Power of Attorney filed November 20, 2003.

THEY 1 0 2005

Correction

U.S. Patent Application No. 10/716,599 Attorney Docket No.: 57983.000119 Client Reference No.: 15725ROUS02U

The attached Certificate of Correction Forms (PTO-1050) indicate the type and location of an error which occurs in the above-identified patent. The error includes:

On the face of the patent in the title section [54], replace "MULTIPLAYER" with --MULTILAYER--.

At Col. 1, line 3, in the title, replace "MULTIPLAYER" with --MULTILAYER--.

Ιt is respectfully submitted that the error typographical error of the U.S. Patent and Trademark Office, and no thus fee is required.

Please charge any shortage in fees due in connection with the filing of this communication to Deposit Account No. 50-0206, and please credit any excess fees to such deposit account.

Respectfully_submitted,

Hunton & Williams LLP

Thomas E. Anderson

Registration No. 37,063

TEA/vrp

Hunton & Williams LLP 1900 K Street, N.W.

Washington, D.C. 20006-1109 Telephone: (202) 955-1500

Facsimile: (202) 778-2201

Date: October 4, 2006

OFT 1 0 2005

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,107,673 B2

DATED : September 19, 2006

INVENTOR(S): Herman Kwong, Luigi Difilippo, and Larry Marcanti

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title section [54]

Replace "MULTIPLAYER"

With --MULTILAYER --.

At Col. 1, line 3, in the title, Replace "MULTIPLAYER" With --MULTILAYER--.

MAILING ADDRESS OF SENDER:

PATENT NO. 7,107,673 B2

HUNTON AND WILLIAMS LLP 1900 K Street, NW, Suite 1200 Washington, DC 20006-1109 Attorney Docket No.: 57983.000119

No. of additional copies

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the complete application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

PTO/SB/44 (O7-03)
Approved for use through 01/31/2004. OMB 0651-0033
U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,107,673 B2

DATED : September 19, 2006

INVENTOR(S): Herman Kwong, Luigi Difilippo, and Larry Marcanti

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title section [54]

Replace "MULTIPLAYER"

With --MULTILAYER --.

At Col. 1, line 3, in the title, Replace "MULTIPLAYER" With --MULTILAYER--.

MAILING ADDRESS OF SENDER:

PATENT NO. 7,107,673 B2

HUNTON AND WILLIAMS LLP 1900 K Street, NW, Suite 1200 Washington, DC 20006-1109 Attorney Docket No.: 57983.000119

No. of additional copies

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the complete application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.